RCRA	OUTREACH & DATA VE	ERIFICA	TION SITE	VISIT CHECKLIS
Site visited by: John Maher / Etra Tech		JEM		date of visit) 3/25/98
EPA RCRA ID#:	IAROBOCO5918 1A00536 (FILE#)	SIC Code(s):		3089
Facility Name: Facility Address Phone No.	Centro Inc. 950 N. Bend Dr. (319) 626-3200	:	City, St,Zip	North liberty IA, 52314
Letters, RCRIS Report and Brochures given to: (name and Title/job description)		Diane Flynn, Vice President		
1. Facility Description:		Monufacturer of polyethylene and nylon molds		
2. What Chemical and/or Industrial Waste (CIW) streams are generated? (List name/type, approx amount generated/mo, final disposition/how disposed)		See ROLA Screening Chacklist		
3. Does the facility classify any of their CIW's as hazardous waste (HW) (Specify which)		Yes _/ No_ See RCRA Screening Checklist		
4. Does the facility conduct any of the following on-site activities: Treatment/Recycling/Burning/Open Dumping/ Landfills/Surface Impoundments? Describe:		No	<u>ن</u>	
5. Are CIW/HW stored on-site?  Describe (material, approx quantity, storage method):		Yes_No_V See RCRA Screening Chacklist		
6. Describe condition of storage containers/tanks (open, damaged, unlabeled, leaking, etc.):		See RCRA Screening Charles		
7. Are incompatibles stored together (acids, bases, solvents, cyanides)? Describe:		Yes	No <u>~</u>	
8. Are there any signs of past spills/releases (dead of stressed vegatation, ground discoloration, stains)? Describe:		Yes	. No_ <u>~</u>	
9. Do any of the on-site chemical and/or CIW/HW management practices concern you? Describe:		Yes	No <u>~</u>	R00090077 RCRA Records Center
10. Recommendations and/or Additingero Observations:				RECEIVED
	JUN 23 1998 RESP	by	data ente	JUN 0 2 1998  ARCM/ENSV

## CENTRO INC. North Liberty, Iowa



Photo No: 3 Direction Facing: North Photographer: Eric S. Monschein

Date: 03/25/98, 1400 Description: Front of facility from visitor parking lot.

2